

**SECRET****PRIORITY 1**

1967 NOV 17 22 03Z

OUT63621

25X **SECRET** 172153Z CITE [ ] 2277  
25X **PRIORITY** [ ]

1. CAMERA B-24 WAS USED ON MISSION G994 FLOWN 16 NOVEMBER 1967.  
PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE AND RESOLUTION WERE GOOD THROUGHOUT FOR BOTH SIDES.

B. 9R SIDE: SLIGHT INBOARD ROLLER CHATTER IS PRESENT INTERMITTENTLY THROUGHOUT. THE POSITION INDICATORS ARE SHARP; HOWEVER, THEY ARE UNDEREXPOSED. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 133 AND HEAT SPLICES OCCUR IN FRAME 882 AND BETWEEN FRAMES 1821 AND 1822.

C. 9L SIDE: POSITION INDICATORS ARE READABLE; HOWEVER, THEY APPEAR UNDEREXPOSED. THE DATA BLOCK IS OVEREXPOSED, NOT SHARPLY IMAGED, AND IS DIFFICULT TO READ. THERE IS A MANUFACTURER'S SPLICE IN FRAMES 661 AND 1115. HEAT SPLICES ARE PRESENT IN FRAMES 12, 72, AND 861.

D. BOTH SIDES: ROLLER CHATTER AND EDGE STATIC IS VERY MINOR AND CAUSE NO IMAGE DEGRADATION. FRAME 1920 IS THE LAST TITLED FRAME ON BOTH THE 9L AND 9R SIDES.

## 3. POSITIVES:

A. PRINTING AND PROCESSING ARE GOOD.

B. PI SUITABILITY IS GOOD THROUGHOUT.

C. CLOUDS OBSCURE APPROXIMATELY 35 PERCENT OF THE MISSION.

GP-1

**SECRET**

END OF MESSAGE

| DISTRIBUTION |         |        |
|--------------|---------|--------|
| By No.       | Office  | Action |
| 1            | File    |        |
| 2            | OS      |        |
|              | SEC BR  |        |
|              | TCS     |        |
|              | CSO     |        |
|              | IFO     |        |
|              | FO      |        |
|              | WFO     |        |
|              | SEC-ICB |        |
|              | WFO     |        |
|              | IAS     |        |
|              | PAG     |        |
|              | DIAXX-4 |        |
|              | SPAD    |        |
|              | NSA-LO  |        |
|              | DIA-AP  |        |

NGA review(s) completed.

**SECRET**

GROUP 1  
Excluded from automatic  
downgrading and  
declassification